



Ramtox Environmental Company


TEL: 818-992-8981 FAX: 818-992-8982 WWW.RAMTOX.COM
 EMAIL: George@ramtox.com 7538 Carmenita Ln, West Hills, Ca 91304

APRIL 15, 2007

VOLUME 1, ISSUE #3



PHASE II EVR INSTALLATION DEADLINE



Pre/Post-Transaction Screen Form Guidelines are developed by our business investment compliance experts.

This week's investments opportunity is:

Independent gas station with car wash
 gas sales : 250K gal
 C-store sales : 37K
 car wash : 8K
 asking : 3.5 million

Independent gas station with C-store
 gas sale : 250K gal
 C-store : 45k
 asking : 3.2 million

For more Information, please contact George at

818-429-6184

PHASE II EVR INSTALLATION DEADLINE

Gasoline Dispensing facilities are mandated to install PHASE II EVER system as following CARB's Timeline. Currently, only Healy System is the approved phase II EVER system in California.

<i>Gasoline Throughput</i>	<i>Phase II EVR</i>	<i>CARB EXECUTIVE ORDER</i>
<i>Gasoline sales Greater than 1.8 Million gallons per year</i>	<i>April 1, 2009</i>	<i>VR-202-B</i>
<i>Gasoline sales between 600,000 to 1.8 million gallons per year</i>	<i>April 1, 2010</i>	<i>VR-202-B</i>
<i>Gasoline sales less than 600,000 gallons per year</i>	<i>NOT RESTRICTED</i>	<i>NOT APPLICABLE</i>

A Recent test performed by three balance manufacturers to certify an equivalent Phase II EVR Balance System failed the pressure test. These balance systems, which failed the pressure limit, were designed to comply with CARB'S EVR performance and standards. If you are interested to start converting your site to Phase II EVR, please give us a call for a quote.

PACKAGE DEAL TESTING AND COMPLIANCE TRACKING SERVICES

For AQMD & UST testing, repair, groundwater monitoring, soil testing, and maintenance, we offer multiple package deals. Our compliance tracking system will alert you the AQMD and UST testing due dates.

NEW : FUEL ALARM AND POSITIVE SHUT DOWN PREVENTION PROGRAM

In month of December we sealed five sites by replacing torn gaskets on the tank lids and resealed the top tank. None of these sites triggered fuel alarm when we had the rainstorm in December. If you want to seal your sumps and install new gaskets to stop intrusion of rain water in sumps, please contact us at 818-992-8981.

